

## Nortel 922-071 Exam

**922-071: BCM50 Rls.3.0 & BCM200/400 Rls.4.0 Config & Maintenance**

**Practice Exam:** 922-071 Exams

**Exam Number/Code:** 922-071

**Exam Name:** BCM50 Rls.3.0 & BCM200/400 Rls.4.0 Config & Maintenance

**Questions and Answers:** 30 Q&As

**( Other Nortel Certification )**



Exam : [922-071](#)

We provide professional Nortel 922-071 exam information and free demo for 922-071 certification exam's PDF. It is the best and the latest Nortel Practice Exams. Download our 922-071 PDF. We are committed to your ongoing success. Free PassBible 922-071 exam and 922-071 Q&As are constantly being updated and compared to industry standards.

### **PassBible Test tool's advantages:**

#### **High Quality and Value of 922-071 exam**

PassBible Nortel Other Nortel Certification 922-071 Practice Questions is developed and finished by Nortel technical team , cover every field of the exam . Besides, we have verified 922-071 answers,almost 100% correct.

#### **100% Guarantee to Pass 922-071 Exam**

We promise to give you FULL REFUND if you fail the Other Nortel Certification 922-071 certification(Nortel Certified Network Associate) with the use of our PassBible testing engine.

#### **922-071 Self Test Mode**

PassBible provides a simulated and interactive environment where you can test your knowledge and skills about 922-071 to ensure enough assurance in real testing center.

#### **Periodic Updates of PassBible 922-071**

Once there is some change on Nortel 922-071 exam, we will update it timely, and the product you buy will be updated within 90 days for free.

#### **Professional and Efficient Service**

We offer 7\*24 customer support via diverse channels: LIVE CHAT,MAIL.Expecting the communication with you about IT certification.

This 922-071 pdf demo do not include the questions and answers's picture.

Exam : Nortel 922-071

Title : BCM50 Rls.3.0 & BCM200/400 Rls.4.0 Config & Maintenance

1. A customer added new floor space to the warehouse, and had some electricians run cable to the new area. When a T7316 set is connected, the line indicators flash continually. The set is about 1950 feet (600 meters) from the BCM. Which step can be taken to correct the problem?

- A. Use a SAPS with the T7316E.
- B. Replace the tele phone with a T7100.
- C. Turn the loop length option in Element Manager to "long".
- D. Advise the customer that the maximum distance is 1500 feet.

Answer: A

2. Which BCM200/400 specialized module lets the BCM share its connection to a Universal TI network with a WAN to provide a combination of voice and data channels?

- A. Fiber Expansion Module (FEM)
- B. Digital Drop and Insert MUX (DDIM)
- C. R2 Multi-Frequency Compelled module (R2MFC)
- D. Digital enhanced cordless telecommunications module (DECT)

Answer: B

3. What is the maximum number of Enhanced Key Expansion Modules (E KEMs ) supported by the BCM50 system ?

- A. 1 E KEM per IP tele phone and 10 sets per system
- B. 2 E KEMs per IP tele phone and 12 sets per system
- C. 3 E KEMs per IP tele phone and 16 sets per system
- D. 5 E KEMs per IP tele phone and 12 sets per system

Answer: D

4. Which specialized module connects a maximum of six Norstar expansion modules to the BCM200/400?

- A. Fiber Expansion Module (FEM)
- B. Digital Drop and Insert MUX (DDIM)
- C. R2 Multi-Frequency Compelled module (R2MFC)
- D. Digital Enhanced Cordless Telecommunications module (DECT)

Answer: A

5. A customer with a BCM400 has a requirement of one T1, six PSTN analog lines and 12 digital telephones. What are the minimum Media Bay Module (MBM) requirements?

- A. one DTM and one G8X16
- B. one BRIM and one GASM8
- C. one GATM8 and one G4X16
- D. one GATM4 and one DSM16+

Answer: A

More [922-071 exam](#) information

### Related Nortel 922-071 Exams

[922-109](#) *Communications Server 1000 RIs.6.0 BARS/NARS*

[922-101](#) *Communication Server 1000 Linux Platform Architecture*

[922-111](#) *Communication Server 1000 to RIs.6.0 Upgrades for Technicia*

[922-081](#) *CallPilot RIs.5.0 Networking*

[922-457](#) *CallPilot RIs.4.0 Unified Messaging Exam*

[922-104](#) *Communication Server 1000 RIs.6.0 Upgrades for Engineers*

[922-071](#) *BCM50 RIs.3.0 & BCM200/400 RIs.4.0 Config & Maintenance*

[920-110](#) *NCCSS SL-100 Maintenance Certification Exam*

[922-098](#) *Communication Server 1000 RIs.5.0 Troubleshooting*

[920-806](#) *Nortel Advanced Data Networking Technology*

[920-805](#) *Nortel Data Networking Technology*

[920-220](#) *Nortel Converged Campus ERS Solution*

[920-502](#) *nncss-optera metro 3000*

[920-569](#) *nncds-optera metro solutions*

920-246 Nortel WLAN 2300 RIs.5.0 Implementation & Management

---

920-520 Nortel Agile Communication Environment (ACE) RIs. 1.x Design & Engineering

---

922-094 Communication Server 1000 RIs.5.0 Dialing Plan Design & IP

---

922-099 Communication Server 1000 RIs.5.0 Linux Platform Base & App

---

920-199 BCM50 RIs. 2.0 & BCM200/400 RIs. 4.0 ICM

---

920-111 NCSS-VoIP Communication Server(CS)2100

---

### **Other Nortel Exams**

920-215      922-021      920-176      920-241      922-062      920-163      920-469      920-465

920-127      920-450      922-092      922-093      920-804      920-134      922-031      922-110

920-240      920-530      920-345      920-471